CITY OF BALTIMORE WET SMOKE AND DYED I	Page 1 of 3				
Sewershed: Low Level Subsewershed: 44	Company: REI/DRAYCO	Date: 09/03/2008			
Test Type: Smoke	Ground Condition: Dry: X Damp:_ Wet:_	Supervisor: E.R. Crew: 04			
Manhole ID: S19I036MH	Test ID: 1029-591	Notifications Made:X_ Residents, Fire, 311			

Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)



	CITY OF BALTIMORE WET SMOKE AND DYED						EE				Page 2 of 3
,	Sewershed: Low Level Subsewershed: 44	Company: REI/DRAYCO					CO	Date: 09/03/2008			
	Test Type: Smoke		Ground Condition: Dry: X Damp:_ Wet:_					Supervisor: E.R. Crew: 04			
Ma	anhole ID: S19I036MH		Test ID: 1029-591					Notifications Made:X_ Residents, Fire, 311			
Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)											
Defect No.			Source Type			Sector	Drai	nage ea			Photo Number
1	2174 HOLLINS ST.		02	08	8	02	C)5	02		1029-591_OB01-01.jpg
				-							
			OB			ION CO	DES	_		1	
04 14	Source Type	04	D1 C	Loca		Nan Da			Sector	04	Severity
	ain Sewer 10 MH Frame ervice Line 11 Storm Drain		Paved C	_		Non-Pa Field/W			Public Private		No Smoke Trace
	eanout 12 Catch Basin		Asphalt Paved C				บบนร	02	rnvale		Moderate
	ownspout 13 Storm MH		Drivewa			Golf Co	urse				Major
	rea Drain 14 Storm Ditch		Sidewal			Other	3.30			<u> </u>	
	wy. Drain 15 Excavation		Curb			-					
	air. Drain 16 Water Line		Yard - F	ront							
	ound. Drai 17 Tele. Pole		Yard - B								
09 Blo	dg. Interio 18 Other	09	Yard - S	ide							

CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY LOW LEVEL SEWERSHED

BALTIMORE CITY PROJECT 1029 REI/DRAYCO

Unique Test ID: 591 Date: 09/03/2008 Basin: LL - 44 Manhole ID: S19I__036MH Defect No: OB01 Supervisor: E.R. Crew: 04 Dye Test Recommended: N

Location: 2174 HOLLINS ST.

Source Type: 02 Service Line Sector: 02 Private

Location: 08 Yard - Back Severity: 02 Trace Drainage Area: 5

Comments: SMOKE IS COMING FROM THIS HOLE IN CURB ADJACENT TO TREE.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01 Filename: 1029-591_OB01-01.jpg